WIRE BROOM


Handle
Shank
Screws or bolts
Brush
Heavy Steel
Flat Bristles