

## FIX-N-FAX #35

### CALIFORNIA DEPARTMENT OF FORESTRY AND FIRE PROTECTION

No. 35

**Equipment Standard**

**Mandatory Compliance**

Date: September 1983

#### **Cooling Fan Failure 1976/77 FY Dodge Stakesides**

The engine cooling fan on one of the above stakesides lost a blade, and further inspection revealed that several of the blades were starting to fail around the rivets.

It appears the failure begins where the rivets become loose and let the blades flex in excess of their design capabilities.

The following vehicles should be checked immediately for damaged fan blades and replaced if necessary, and at all safety inspections.

3 X 187	E-845081	Region 1
3 X 090	E-846080	Region I
3 X 035	E-845078	Region I
3 X 066	E-846071	Region I
3 X 084	E-846075	Region I
3 x 085	E-846076	Region II
3 X 122	E-845079	Region II
3 X 152	E-846074	Region III
3 X 086	E-846085	Region III
3 X 080	E-846086	Region III
3 X 027	E-846088	Region III
3 X 166	E-846087	Region III
3 X 168	E-846073	Region III

3 X 186	E-846072	Region III
3 X 019	E-846077	Region IV
3 X 083	E-846082	Region IV
3 X 007	E-846083	Region IV

[\(see FIX-N-FAX INDEX\)](#)