

FIX-N-FAX #47

CALIFORNIA DEPARTMENT OF FORESTRY AND FIRE PROTECTION

No. 47

Date: September 1978

Revised: December 1985

Accumulok Replacement Parts

Vacuum operated Accumuloks are no longer being manufactured; however, repair parts are still available from:

P.T.O. Sales and Service
12127 Park Street
Cerritos CA 90701
(213) 926-7802

The unit will have to be replaced with Cable Actuated Control Accumulok Assembly #02-665-009, available locally or through above referenced vendor.

ACCUMULOCK VACUUM LINES

Field units are reporting that the plastic vacuum lines used on the Accumulok are being destroyed by engine manifold heat or extreme heat in other areas. Lines exposed to these conditions should be replaced with copper tubing or composition-type vacuum hose, taking care to route away from manifold areas and securely clamped to avoid effects of vibration or chaffing.

Should one of these control lines fail, the service brakes are not affected except that Accumulok cannot be released from the driver's compartment. It then becomes necessary to crack a brake bleeder valve to release brakes.

[\(see FIX-N-FAX INDEX\)](#)