

## FIX-N-FAX #68

### CALIFORNIA DEPARTMENT OF FORESTRY AND FIRE PROTECTION

No. 68

Date: January 1982  
Revised: December 1985

#### **No. 1 and No. 5 Fire Engines (1977/78 and 1978/79 FY)**

One or both of the 1 ½ inch swing check valves illustrated on the reverse (no illustration available) installed on some of the above described vehicles, may be sub-standard and should be replaced.

Since most swing check valves being used have no identifiable markings, the only sure way to determine if valve needs replacing is to remove the dome and inspect the flapper.

If the flapper has a neoprene seat, the valve should be replaced with one of the following:

#### SPECIFICATIONS:

1 ½ inch all brass "Y" pattern valve screwed, swing check 400 psi W.O.G.

Grinnel #	3350 - 1 ½
Stockham #	Fig. B - 345 - 1 ½
Crane #	36 - 1 ½
Kitz #	Fig. AKR 1 ½X 3 Code 04112

Available from local plumbing supply centers.

(see [FIX-N-FAX INDEX](#))