

FIX-N-FAX #70

CALIFORNIA DEPARTMENT OF FORESTRY AND FIRE PROTECTION

No. 70

Date: August 1973
Revised: December 1985

Live Reel Brake

Early model Hannay live reels used a set screw to attach the brake shoe ring to the reel shaft and was difficult to keep tight. An easy fix is to arc weld this shoe to the shaft as pictured (no picture available).

LIVE REEL REPLACEMENT PARTS

All components and repair parts for Hannay live reels are now available from:

Grumman Emergency Products
661 Garcia Avenue
Pittsburgh CA 94565
Telephone: (415) 439-2011

BACK PUMP FILLER

The back pump filler handle on some Models #1 and #5 fire engines is exposed to the brush wherein the valve may be inadvertently opened. Valve should be turned around so that valve handle is toward right side of engine and handle points upward when open.

¼TURN VALVES

Whenever possible, handles on ¼turn valves should be positioned so that handle is in off position when 90 degrees to flow of water.

OUTBOARD TANK FILLER SHUTOFF

A Gismo Type shutoff valve may be installed on the Models #1 and #5 fire engines' tank filler (filler as described in Fix-N-Fax), when desired.

Available at: Western Fire Equipment Company
440 Valley Drive
Brisbane CA 94005
Telephone: (415) 467-5650

Gismo 1 ½NH threads =

(see [FIX-N-FAX INDEX](#))