

FIX-N-FAX #80

CALIFORNIA DEPARTMENT OF FORESTRY AND FIRE PROTECTION

No. 80

Equipment Standard

Mandatory Compliance

Date: September 1990

Light Bar Visibility - Models #1 and #5


Region IV has brought to light a safety issue reference to those CDF Model 1s and Model 5s equipped with light bars mounted on the square tubing structure and attached to the rear of the cab.

Those units have alley lights mounted on top of the structure, at the same level as the light bar, thus blocking the view of the light bar from the side.

In the interest of safety, all alley lights shall be moved from top mounting to an under side mounting location on the tubing structure, thus allowing full side visibility.

To accomplish this, special tabs will need to be attached to the underside of the horizontal square tube, at each end. This will permit the light to be offset, allowing clearance between the light housing and cab.

This change is within regional authority and, for specific details, please contact the local Fleet Manager.



(see [FIX-N-FAX INDEX](#))